Notice



	"""
CORRECTION PRODUCTION CH.	ANGE
SERVICE FLASH ADD INFORMATION	FILE NO.
Please add this notice to the Service Manual listed below. REVISION 0	
Category: COLOR TELEVISION	Date: FEBRUARY / 07 / 2012
Model: Effective from : Chassis No	
Destination: U.S.A. / CANADA REF : No. SM780185-04	
NOTE: Match the Chassis No. on the unit	's back cover with the Chassis No. in the Service
NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service	
Literature is required. This chassis is similar to Chassis No. P50741-00. Only the	
difference Service Information is given in this manual. For detailed Service Information,	
refer to the Original Service Manual and Notices for Chassis No. P50741-00 used in	

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

Model DP50741 (SM780185).

The are no changes.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

3. PWR ON LED POSITION CHANGE

Before (J4JE): Right side Current (J4JEG): Left side

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

© Sanyo Manufacturing Corporation 2012

February 2012 SMC